




## **Ford Mondeo Model year: from 05.2002**

### **Low-pressure service connection**

On the above-mentioned vehicles manufactured since 02.05.2002, it is no longer necessary to remove the right-hand wheel house lining to reach the low-pressure service connection.

The modified wheel house lining has a pre-marked maintenance opening through which the service connection is accessible. When the service unit is connected to the low-pressure side for the first time, the maintenance opening must be cut in along the marking. Please proceed as follows:



- Lift the vehicle
- Cut in the wheel house lining carefully along the marked lines (drawing, pos. 1)
- Remove the screw (drawing, pos. 2)
- Open the maintenance opening (drawing, pos. 3)
- Once the maintenance work has been completed, close the opening and screw in the screw.