



## ***Ford***

### ***Mondeo III***

***Model year : 10.2001–04.2002***

***Engine: 2.0 TDCi***

## ***Focus***

***Model year: 05.2001–04.2002***

***Engine: 1.8 TDCi***

**Engine will not start / runs roughly.  
Preheat control lamp flashes**

If there are complaints with these vehicles that the engine will not start anymore/runs roughly and the preheat control lamp flashes, one possible cause is a defective diesel high-pressure pump. Due to excessive wear on the cam ring and the rollers, the required pressure can no longer be built up in the fuel system. The metal abrasion can get into the injection system and lead to the injectors failing. To resolve the problem, in addition to a modified high-pressure pump, the injectors must also be replaced. Vehicles made from April 2002 already have a modified high-pressure pump.

Note: When repairing the fuel system, it must be ensured that all dirt particles are removed from the system.