

© Hella KGaA Hueck & Co., Lippstadt

24. Juni 2002



1-1

Ford Transit with 2,5 ltr. Diesel engine, Build year 10.96 – 02.98

Warning light – water trap illumination and/or blown fuse Nº 7

If the warning light – water trap illuminates, although the water in the water trap of the fuel filter is drained, and/or the fuse № 7 has blown several times, the cause could be a short circuit in the warning light cable. In this case, the warning light cable close to the positive starter cable must be checked.

To rectify the problem the cable must be repaired and fixed with a cable tie, to prevent a new damage.

Bulletin

