


© Behr Hella Service GmbH, Schwäbisch Hall

01. Oktober 2005

## Honda Civic, from model year 2001 Jazz, from model year 2002

## **New clip connection**

New clip connections are being used in the area of the evaporator in the above-mentioned vehicles. These connections consist of a retaining clip (Pos. A) and safety ring (Pos. B) and serve to form a connection between the pipeline and the evaporator. The connection can be loosened only by cutting the safety ring along the line shown (Pos. C). New clip connections must be used during assembly. Care must be taken to ensure that the flat collar of the retaining clip is mounted in the direction of the O-ring.



Bulletin





1-1