



BULLETIN

Honda Civic VII Model year: 2001–2005

Replacement of the cabin filter Disinfection of the evaporator

Proceed as follows to access the cabin filter on the vehicles listed above and perform a disinfection of the evaporator:

- Dismantle the glove compartment (figure 1)
- Remove the cover of the fan housing (figure 2)
- Pull out the cabin filter (figure 3)
- Insert the spray lance to disinfect the evaporator surface (figure 4)



Figure 1




Figure 3



Figure 2



Figure 4