



# BULLETIN

---

## Lancia Ypsilon Model year: 2003 - 2011

### Air-conditioning system/Display for outside temperature

The vehicles mentioned above may experience a failure of the display for outside temperature. This affects the control of the air-conditioning system.

The outside temperature sensor is housed in the left-hand wing mirror (see figure). A broken cable in the mirror can cause a failure in the temperature display. This leads to control problems when using the air-conditioning system.



We should proceed as follows to rectify the problem:

- Remove the rear cap from the mirror
- Remove the actuator motor
- Remove the mirror cover
- Dismantle the mirror housing
- Locate and repair the damaged part of the wiring harness
- Perform a functional test
- Re-assemble the mirror