




Mazda 626 IV (GE) Build year 1991-1998 with factory installed air-conditionung

Leaking condenser

On some of the above -mentioned vehicles a leakage on the condenser can occur. Often the leak is in the lower area. If a refrigerant loss is established, it's recommended to spray this area with a leak detection spray (see picture). Alternatively the leak detection can be carried out with an electronic leak detector or a contrast medium (dye).



Bulletin