



## **Mercedes**

**Type 129, 140, 202, 210, 215, 220, 463**

**Model year: up to 08/1999**

### **Illogical regulation of air conditioning system / air conditioning system not functional**

In the case of the above-mentioned vehicles it may occur that the air conditioning system reacts illogically, that the EC-LED illuminates without the button being pressed, or that the air conditioning system does not work at all. This can be caused by a faulty evaporator temperature sensor. The absorption of moisture causes the sensor to transmit false values to the control unit. The temperature sensor was modified by the factory from mid-August 1999.

**Bulletin**