



Mercedes

Type: 124, 129, 140, 202, 210

With Becker radio "MB Classic"

Radio does not work

Aerial extends and retracts automatically

With the above-mentioned vehicles fitted with the "MB Classic" radio (Becker BE 2010), with traffic news and RDS, the following faults can occur:

- Radio can no longer be operated
- Display blank
- Not possible to switch off
- Aerial extends and retracts continually

If any of the above-mentioned faults occurs, there is a fault in the software. For the fault to be eliminated the radio must be replaced. Radios from serial number BE 2010S 1110001 onwards already have an updated software version.