



Mercedes-Benz Sprinter

Air-conditioning system without condenser fan

On some of the above-mentioned vehicles the use of a condenser fan has been omitted. The following pressure conditions are caused by this, particularly at high outside temperatures, but accept the following as "normal":

Low pressure: up to 3 bar

High pressure: up to 25 bar

Consequently the measured air outlet temperature can be higher than "normal".

