Bulletin



© Hella KGaA Hueck & Co., Lippstadt

14. Oktober 2005

Mercedes W124, W129, W140, W202 With daytime running light as a standard series fitting

Daytime running light does not switch off

If with the above-mentioned vehicles the daytime running light does not switch off when the engine has been stopped, this can be caused by a faulty daytime running light control unit.

The following vehicles with these chassis numbers are particularly affected by this problem:

WDB 124 XXX X C from 179243 to 187935

WDB 124 XXX X F from 303037 to 304985

WDB 129 XXX X F from 109653 to 110888

WDB 140 XXX X A from 221306 to 225967

WDB 202 XXX X F from 149781 to 161884



