



## **Opel Astra G Zafira With engine Y20DTH, Y20DTL, Y22DTR, X20DTL**

### **Loss of engine power, engine in limp-home mode.**

If there are complaints with these vehicles that the engine loses power during or after long drives in rain, or that it goes into limp-home mode, one possible cause is the air filter reaching its water-saturation limit. As a result, the function of the air mass sensor is restricted and the above-mentioned faults occur. In order to eliminate the fault, Opel offers an additional water-drain hose, which must be installed in the lower part of the air-filter housing.

The required spare parts can be obtained via the local dealer.

**Bulletin**