## Page 1 of 1

© HELLA KGaA Hueck & Co., Lippstadt

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, pictures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.

2016

## BULLETIN

## Opel Astra H Model year: 2002 - 2009

## Loss of refrigerant Condenser damaged and leaking

If refrigerant loss is observed on one of the vehicles listed above, special attention should be paid to the condenser.

Failure of the fins can cause instability in the condenser network. Vibrations can cause contact with other components. This will damage the condenser (Figure 1) and, in some cases, cause it to leak.

The condenser may also come loose from its holder and drop onto the beam (Figure 2). This can also cause leaks.



Figure 1



Figure 2



