

© Hella KGaA Hueck & Co., Lippstadt

29. Juli 2002

uli 2002 1-1

Opel Sintra build year from 1999 Interior lamp stays on

Interior lamp stays on after closing the door, and can only be turned off manually.

If the complaint is as above there can be several fault causes.

- Dimmer control switch of the instrument panel has been turned too far (overcam).
- Door contact switch on the sliding doors (no electrical connection).
- Jammed wiring harness below the passenger seat.
- Check the dimmer control switch for operational function, if necessary replace.
- Remove and dismantle the door contact switch (by pressing back the cam of the contact) of both sliding doors. Clean the contacts, remove dirt and grease, if necessary bend them into the normal position to ensure an optimal contact. Check the electrical connection for corrosion.
- Damage to the wiring harness, must be repaired.



Bulletin

