



Opel

Vectra C

Model year: 2006 - 2008

Engine: 2.8i V6 (169 KW + 184 KW)

Loss of coolant

On the above mentioned vehicles a loss of coolant may occur due to a faulty coolant expansion tank.

The problem has already been addressed by the vehicle manufacturer, the vehicles checked during a servicing campaign and the expansion tank renewed.

It must be assumed, that for a variety of reasons not all vehicles have been checked and/or repaired.

Tip: on the replacement of the tank, the cap should also be checked and renewed if necessary.

Please take this information into account, particularly in relation to complaints about coolant loss.

Bulletin