



Opel Vectra-B ***All models***

Poor or no functioning of the remote control for the central locking.

If there are complaints with these vehicles that the remote control for the central locking does not work or only works poorly, one possible cause is insufficient contact force between the battery and the contact stud in the hand-held transmitter.

To eliminate the fault, the contact stud must be bent a little further in order to increase the contact force. To exclude the possibility of a flat battery as the cause, this should be replaced at the same time.

Bulletin