



Opel Vectra B

ABS lamp lights up, fault code in control unit.

If there are complaints with these vehicles that the ABS lamp lights up and fault code 37 (brake light switch circuit) is stored in the ABS control unit, possible causes are a contact resistance on the earth wire for the brake lights, or an oxidised brake light bulb socket.

To eliminate the fault, the bulb sockets should be checked and the drop in voltage on the earth wire from the brake lights to the bodywork earth point should be measured with the brake lights switched on.

Oxidised bulb sockets should be replaced and a poor earth connection repaired. Following this, the fault code in the ABS control unit must be deleted.