



## **Opel Vectra B From model year 1996**

### **ABS lamp illuminates, fault code 37 in the control unit.**

If there are complaints with these vehicles that the ABS warning lamp illuminates and fault 37 is stored in the ABS control unit, a poor ground connection may be the cause. Fault code 37 means "Interruption – supply line to stop light switch" The ground connection at point 6 in the vehicle luggage compartment is affected (see illustration).

To eliminate the fault, the ground connection must be cleaned.

After this, the fault memory must be deleted and the system must be checked to make sure that it is working perfectly.

Interior view - end face of luggage compartment

