

© Hella KGaA Hueck & Co., Lippstadt

24. Mai 2002

## Opel Vectra B, build year up to 1996

## Interior lamp light up permanent

the mounting screw of the right sun visor.

If the coustomer complains about permanent illumination of the interior light the cause can be due to the following: The wiring to the right rear reading light can be damaged by

To rectify the problem, repair the wiring and fix it to a place where it can not be damaged.



## 

