



Opel Vectra B Model year: 1996 to 06/1997

Radio malfunction

In the case of the above-mentioned vehicles there can be functional problems with radio systems with remote control buttons. These can occur as follows:

- When the radio remote control button “station search” is pressed, the volume increases
- When the radio remote control button “increase volume” is pressed, the volume decreases
- The switchover button “radio/cassette” doesn’t work

This can be caused by faulty remote control units. These must be replaced in such cases. Remote control units manufactured after 03.06.1997 or with blue or green colour marking (marking is on the underside) have already been modified and can almost always be excluded as a cause of the fault.