

Bulletin

Opel Vivaro

Model year: 2010

Vehicle Identification Number: up to

WOLF7BHB6BV617781

Engine oil pressure indicator light on

In the above vehicle, the indicator light for the engine oil pressure may light up while the engine is running. This may indicate a defect in the electrical connection of the oil pressure switch.

To remedy this, the plug-in connection should be checked for soiling, damage and correct positioning.

The plug-in connection may need to be cleaned or replaced as appropriate.

