



Peugeot 307 Model year 04/2002, with 1.4 l / 55 kW engine

Engine does not start up, engine warning light comes on.

If on this vehicle the engine does not start up and the engine warning light comes on, one possible cause is the crankshaft sensor. If a fault memory read out is taken using a diagnosis unit, the fault code "P 1335 = camshaft sensor" is stored. If the camshaft sensor is checked, it will be found that this is OK. In this case, the crankshaft sensor is not fitted correctly in the borehole, and the control unit is mixing up the two sensors.

The crankshaft sensor has to be removed, cleaned and inserted in the borehole correctly again. Following this, erase the fault memory.