



Peugeot

406 + 607

Model year: 11.1999–09.2003

Engine: 2.0-litre HDi + 2.2-litre HDi

Vehicles without EOBD

Starting problems / Preheat relay

Starting problems may occur in the case of the above-mentioned vehicles. Sometimes, the engine will not start at all anymore. One possible cause is a defective preheat relay (see photo). In the event of a complaint, the relay should be checked and, if necessary, replaced. The Hella spare-part no.

is

4RV 008 188-381.

The vehicle manufacturer has notified all vehicle keepers affected and has asked them to have their vehicles checked at an authorized dealer. It must be assumed that there are nevertheless still vehicles in circulation which, for a variety of reasons, have not been checked or modified. Please take this information into account in the event of complaints in connection with starting problems.

