



Chrysler PT Cruiser Build year till 04/2000

Noises from the left and /or right front door.

If, on this vehicle, noises from the left and/or right front door can be heard, a possible cause could be the water shield, touching the loudspeaker. To reproduce the customers complaint, the radio should be switched to medium volume . Check each loudspeaker for noise using the balance control. If a noise is present, to solve the problem the water shield must be renewed. For that consider the following steps:

- Remove the front door panel.
- Remove the loudspeaker.
- Remove the old water shield and fit a new one.
- Refit the loudspeaker and the door panel.
- Check the function and for noises.
- If necessary repeat the steps on the other door.