



Renault 21 / Nevada (L48 / K48)

Air conditioning system inoperative

In the case of the above vehicles with the production numbers listed below, refrigerant loss may occur due to a damaged low-pressure line. This then leads to failure of the air conditioning system. If loss of refrigerant is detected, the low-pressure line must be checked for damage or leaks. While doing this, the resonance silencer in particular should be thoroughly examined. In the event of damage, the low-pressure line must be replaced with a modified version (without resonance silencer).

Type	Production Number
L48 X	R 008000 to R 010000
K48 K	H 013093 to H 013435
K48 R	H 000755
K48 A	H 009887 to H 013924
K48 O	H 020150 to H 029099
K48 7	H 001712 to H 001784
S48 O	H 001573 to H 002317

Important note:

The production number is not the chassis number. It can be found on the vehicle identification plate. On vehicles prior to production year 1996 the plate is oval and is located in the engine compartment. The production number is stated in the penultimate row of numbers. From 1996, the vehicle identification plate is square and is located on the B-pillar on the passenger side. The production number is stated in the first row, on the right.

Bulletin