



Renault Kangoo ***All models with diesel engine***

Poor performance, engine warning light comes on.

If there are complaints with these vehicles that the engine performance is poor and that the engine warning light comes on, one possible cause is an oxidised air flow meter. The reason for the oxidised air flow meter is water penetration. The fault code "air flow meter" is stored in the fault memory. Due to a leak in the area of the two-part plastic panelling in the wheel housing, road spray penetrates the intake area of the air filter. This leads to the oxidation of the air flow meter described above.

To eliminate the leak, the two-part plastic panelling must be fastened in the upper area to prevent road spray from penetrating.

In addition, the air flow meter must be replaced. The necessary spare parts can be found in the Hella Electronics catalogue.

Bulletin

