



## **Renault Laguna 2** **Built between: 07.2001-05.2002**

### **ABS/ESP warning light comes on**

In the case of the above-mentioned vehicles, the ABS/ESP system can fail. Linked with this is the ABS/ESP warning light coming on. The fault can be caused by water penetrating the ABS/ESP plug on the control unit. This plug be cleaned/dried if necessary and protected against repeat penetration of water. The earth connection of the control unit must also be checked. All the above-mentioned vehicles with brake assistant can be affected by the fault.