



## **Renault Laguna 2 Model year: from 2001 With electronically controlled compressor**

### **Poor cooling performance of the air-conditioning system**

If there should be complaints about the cooling performance of the air-conditioning systems with the above-mentioned vehicles, the cause is often not a faulty compressor. Regulation of the compressor is usually electronic. The electric control valve in the compressor (photo) is triggered by the engine or air-conditioning control unit. If examination of the air-conditioning system should reveal that there is no or only a poor cooling performance and that illogical system pressures occur at the same time, a software fault could be responsible. Such cases can be remedied by re-programming the control unit. Contact with a Renault dealer should be sought for this purpose.

**Bulletin**