




Renault Laguna 2 + Vel Satis

Adapter for service connection


As we already described in the service bulletin "Laguna 2" and "Vel Satis", the air-conditioning system has only a low pressure-sided service port. However, this has the dimensions of a high pressure connection. So that the repeated swapping of the service hoses (on service stations that are not able to evacuate and recharge over the high and low side service port) can be avoided, you have the possibility, to build an adapter with the following Hella service parts (see picture 1). This makes it possible for you to connect the the low pressure-side filling adapter of the service station with the low pressure side of the vehicle (picture 2).



High pressure filling adapter
8PE 351 216-001

Adapter
8PE 351 216-111

Low pressure retrofit adapter
9XD 351 201-831 (10 pcs.)



Pic. 1

Bulletin