



## **Renault Laguna II Special servicing connection**

### **A/C service only practicable on low pressure side with high pressure connection**

The Renault Laguna has only one service port for the whole a/c system. Not all service stations are able to recover, evacuate and recharge only over the high or low side service port.

Because on this vehicle only a **high pressure service port** is available fitted to **the low pressure side** (Fig.1) it may be necessary to change the pipes on the service station to service this vehicle. Please read also the Bulletin "Renault Vel Satis – Special servicing connection".

If you are unsure about the method your service station uses, then read the manual, that came with your service station or contact your supplier.




Fig. 1

**Bulletin**