## Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall

01. Oktober 2005

1-1

## Renault Scenic II

## **Evaporator cleaning**

To clean the evaporator in this vehicle, it is necessary to do this by another method as by other cars.

To prevent any damages to the heater fan, the cleaner should <u>not</u> be routed through the air inlet. In this case the cleaner <u>must be</u> routed through the drain pipe from the evaporator.

For this jack up the car and route the extension hose of the cleaner through the drain pipe to the evaporator. The drain pipe can be found on the right side between the axle housing and the floor panel.

For the discharge amount note the instructions of the cleaner/disinfectant or our Technical Information "Airsept". We recommend for cleaning and additional protection "Airsept", Hella article number: 8PE 351 220-001.





