



Renault Twingo (C06 + S06) with engine D4F + D7F

Droning noises

In the case of the above-mentioned vehicles with the production numbers listed below, droning noises may occur when the air conditioning system is switched on.

These noises arise due to the pulsing of the refrigerant, and are transmitted via the refrigerant lines.

To rectify the problem, the low pressure refrigerant line should be replaced with a modified version, and the system should be refilled with 680 g of refrigerant.

Type	Production Number
C06 6	F 484076 to F 657237
C06 8	F 091677 to F 466635
C06 C	F 000010 to F 055925
C06 D	F 000001 to F 019439
C06 G	F 000003 to F 021478
S06 8	F 000303 to F 002520

Important note:

The production number is not the chassis number.

It can be found on the vehicle identification plate. On vehicles prior to production year 1996 the plate is oval and is located in the engine compartment. The production number is stated in the penultimate row of numbers. From 1996, the vehicle identification plate is square and is located on the B-pillar on the **passenger** side. The production number is stated in the first row, on the right.

Bulletin