



## Rover 45

### Condenser fan not working

In the case of the above-mentioned vehicles, a non-working condenser fan can be the cause of faults and/or poor air conditioning system cooling performance.

It is often established that the radiator fan works in an uncontrolled manner, with constantly changing speeds.

It makes no difference whether the engine is cold or warm. In most cases there is a fault in the condenser fan control unit.

The fan itself is OK. Before replacing the control unit, however, the power supply to the condenser fan should be checked by using a circuit diagram.

**Bulletin**