



Saab 9-5 **With air-conditioning**

Noises from the condensed water drain.

If a gurgling noise can be heard in the inside of the vehicle, a possible cause could be the air-conditioning water drains. The drains are located under the vehicle, on the right and left side body sill near the front seats.

To rectify the problem consider the following solution:

Onto the condensed water drains additional one-way valves must be bonded.

To fit the one way valves, clean the water drains and spread glue on them. Then press the one-way valves onto the drains.

The additional one way valves are available from Saab.

