



Saab 900 **build year 1994 - 1995** **with climate control**

Discharged battery

One cause of a complaint for a recurring discharged battery can be a permanently running fan for the interior temperature sensor. The fan should automatically switch off at most, five minutes after the ignition has been switched off. If the fan continues to run, the problem is caused by the A/C control unit. To remedy this, please proceed as follows:

1. Remove the A/C control unit
2. Disconnect the plug from the control unit
3. Construct a bridging cable from pin 1 (black cable, ground) to pin 3 into the connector housing – see pic. (only if pin 3 is vacant – from 1995 already fitted from factory)
4. Connect the plug to the control unit
5. Install the control unit
6. Carry out a function test

