



Seat Alhambra, build year 06/2000

Air conditioning functionless, slow loss of refrigerant.

If on this vehicle the air conditioning is functionless due to missing refrigerant or a slow refrigerant loss is found, a possible cause could be a leaking filter/drier housing. The filter/ drier (1) is integrated with the condenser. The filter/drier housing is sealed by a plastic cap (2). To check for leaks, consider the following steps:

- Evacuate and charge the air conditioning with the exact charge of refrigerant and run the system for a few minutes.
- Remove the plastic cap (2) of the filter/drier housing (**do not remove the snap ring when the system is full**).
- Fill the area (3) above the filter/drier cartridge up this water.
- Check for formation of bubbles.
- If a formation of bubbles is found, the condenser must be renewed.

