Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall 13 October 2006 1-1

Seat Ibiza III (6K1) Model year: 1999 - 2002 With automatic air conditioning

Temperature setting - sudden reset to standard values

The following fault may occur in the case of the above-mentioned vehicles: After a while, the preset interior temperature returns to the standard setting (22 °C), even though a different temperature has been selected. No fault is stored in the air-conditioning control unit. This phenomenon may be linked with the illumination of the service display (inspection). Case are known where after resetting the service display, the air conditioning worked without difficulty again. In the case of complaints in connection with the climate control, make sure that the service display is off.



