20th April 2011

SUZUKI Grand Vitara (JT) Year of manufacture: 2005 to 2008

Buzzing/vibrating noises from the dashboard

Problem:

Various buzzing/vibrating noises coming from the area of the dashboard.

The noises often depend on the engine speed (approx. 1500 min/-1) or occur over uneven road surfaces. Moreover, the noise can disappear depending on the position of the ventilation flaps.

Cause:

Too much "play" in the heating/air conditioning systems - could be due to the ventilation flaps.

Solution to the problem:

Applying foam strips can help to remedy the problem. For further corrective measures and/or information, please consult a Suzuki authorised dealer.

Bulletin



1-1