



## **Toyota**

## **Corolla**

## **Model year: 2005 + 2006**

### **Refrigerant loss / Condenser damaged**

Due to design reasons, the condenser of the above-mentioned vehicles may be damaged by material (e.g. stones) thrown up from the road. This can lead to the condenser becoming leaky. When carrying out air-conditioning servicing, or in the event of a complaint in relation to the air-conditioning system, particular attention should be paid to the condenser. To keep such material away from the condenser, a protective grille is available from the vehicle manufacturer. This grille is retrofitted in the bumper/radiator grille.

**Bulletin**