



Toyota Landcruiser from build year 09/1997

Noises from the a/c unit

On the above-mentioned vehicles unusual noises can be produced with a switched on a/c system. In many cases a vibrating expansion valve causes this. Through the refrigerant, the vibration is transmitted to the high-pressure line. The fluttering noise can be especially heard after engaging the compressor. To fix the problem Toyota offer a special repair kit. On vehicles with the chassis no. before JT3HT05J, the expansion valve and the refrigerant pipe must be changed. In case of vehicles with the chassis no. between JT3HT05J*X0024152 and JT3HT05J*X0034757 only the expansion valve needs to be changed.

Bulletin