



Toyota

Prius II

Model year: 2003–2007

Loss of coolant

With the above-mentioned vehicles there can be a loss of coolant due to a leak in the coolant pump.

The vehicle manufacturer has taken heed of the problem already and initiated a service campaign to remedy it. Since there has not been a recall campaign, however, it must be assumed, that for a variety of reasons not all vehicles have been checked and/or repaired.

The Prius II has three coolant pumps.
In the course of the service campaign, the pump of the inverter/converter unit is checked and replaced.

Please bear this information in mind when complaints are made about loss of coolant.

Bulletin