



Volvo **V70, XC70, S80** **Model year: 2007 - 2009**

Condensate drain

With the above-mentioned vehicles, a faulty air-conditioning condensate drain can lead to the condensate collecting in the heating box. Since an electric booster heater can also be located here, this condensate collection leads to a short-circuit or fire hazard. A remedy is to be provided by installing a modified drain valve.

The vehicle manufacturer has already taken up the problem during a recall campaign. It must be assumed, that for a variety of reasons not all vehicles have been checked and/or repaired. Only authorised garages can see whether the vehicle has been overhauled or not.

Please bear this information in mind when dealing with complaints about water penetrating the vehicle interior and check the condensate drain.

Bulletin