



Volvo

X60, XC70, V70, S80

Model year: 2008 and 2009

Engine: 6+8 cylinder petrol / 5 cylinder diesel

Failure of the radiator fan module

A failure of the radiator fan may occur in the vehicles mentioned above, with the 6 and 8 cylinder petrol engines and the 5 cylinder diesel engine, as the result of a software problem.

This may potentially lead to a reduced cooling capacity of the air-conditioning system and/or an overheating of the engine.

The problem has already been recognised by the vehicle manufacturers and a recall campaign has taken place. It must be assumed, however, that for a variety of reasons not all vehicles have been checked and/or repaired.

In the course of a recall action, the control unit of the radiator fan module is checked/exchanged.

The extent to which modified vehicles are being marked is not known.

Please bear this information in mind when dealing with complaints related to radiator performance or fan function.

Bulletin