



VW Golf 4 (1J) ***model years 1998 – 1999*** ***With automatic air-conditioning control***

Failure of air-conditioning system due to defective radiator fan control unit

In the vehicles specified above, a sporadic failure of the radiator fan control unit can cause a failure of the air-conditioning system.

If a radiator fan control unit with part no. 1J0 919 506 G and a production date between March 16, 1998, and October 26, 1998 is installed, then it should be checked and if need be replaced. The radiator fan control units manufactured after October 26, 1998, have been modified or improved.

Blitz-Info