## BULLETIN



## VW Golf 5 Model year: 2003 - 2007 Engine: 2.0 TDI BKD

## Loss of coolant

The above vehicles may experience a slow coolant loss. It is not possible to determine the cause of this issue at a glance.

To determine the cause of the coolant loss in the TDI motors with the code letters "BKD," proceed as follows:

- Perform a visual check on all the relevant system components (traces of coolant, leaks)
- Perform a pressure loss test on the cooling system
- Check the coolant for contamination (oil)
- Check for coolant in the engine oil

Should the above methods fail to determine the source of the coolant loss, the following potential causes must also be considered:

- Internal leaks in the exhaust gas recirculation radiator (AGR)
- Defective cylinder head gasket
- Hairline cracks in the cylinder head



© HELLA KGaA Hueck & Co., Lippstadt

2016

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, pictures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.

