



VW

Golf 5 Estate + Jetta (1K2)

Model year: 01.2007 to 01.2008

Engine: diesel

Equipment: without parking heater

Fire hazard and function failure through faulty ground cable

With the above-mentioned vehicles, there is a fire hazard due to a faulty, loosely fitted ground cable on the electrical booster heater (PTC). In addition, the function of the booster heater can be affected. The ground connection / ground cable should be checked for overheating damage and for a tight fit on the booster heater. Loose connections must be reattached and damaged cables replaced.

Vehicles from the construction period 08.01.2007 to 09.01.2008 can be affected.

The vehicle manufacturer has started a call-back campaign. It must be assumed, however, that not all vehicles have been checked and/or repaired for various reasons. In the event of such damage, contact an authorised dealer.

Bulletin