



## VW Golf IV

### **Insufficient power of the air conditioning system / radiator fan function**

#### **Problem:**

Insufficient power of the air conditioning system or failure of the radiator fan.

#### **Problem:**

Damaged electric cabling can cause the failure of the radiator fan or the insufficient power of the air conditioning system. No information on the fault was stored in the control unit when the fault memory was read out.

In case of any complaints regarding insufficient power of the air conditioning system or a failure of the radiator fan, please do not only pay attention to the fuses or the plug contacts in the fuse holder.

A damaged cable harness to the radiator fan relay holder (control unit) is also a possible cause of the fault.

#### **Solution of the problem:**

As a remedial measure the damaged cabling must be properly repaired and protected against new damage. For this, some models may require the disassembly of the bottom engine cowling or underrun protection.