

© Hella KGaA Hueck & Co., Lippstadt 24 July 2007 1-1

VW Golf IV estate All models

Tailgate will not close

If there are complaints about the above-mentioned fault, the cause could be a defective servomotor. When trying to close the tailgate, the lock remains open. If the servomotor is defective, the actuating cylinder will not go back to its starting position again. In this case, proceed as follows:

- Remove the tailgate trim.
- Disconnect the linkage on the servomotor (see illustration, points 1 and 2).
- Undo the fastening nuts (see arrows on illustration) and remove the retaining plate with servomotor from the stud bolts.
- Unscrew the servomotor from the plate and replace with a new one.
- Check that the tailgate lock is working.
- Refit all removed parts in reverse order.



Bulletin

