Bulletin



© Hella KGaA Hueck & Co., Lippstadt

23. Dezember 2002

VW Passat build year 1996 Failure of the multi-functional display

Failure of the multi-functional display through malfunction of the voltage regulator

Due to low outsides temperatures the voltage regulator in the instrument panel can malfunction. This can cause the time, trip meter and memory of the multi-functional display to be deleted, "0" appears in the display. If this occurs the remedy is to renew the instrument cluster.

Bulletin

