



VW Sharan **All diesel models**

Loss of coolant

If there are complaints about the above-mentioned fault, leaks at the glow pencils could be the cause. If tolerances are too great, the coolant can escape via the glow pencil thread. In this case proceed as follows:

- Unscrew the glow pencils.
- Remove residual coolant from the glow pencils and the cylinder head. A wire brush can be used for this purpose, for example.
- Make sure the threads in the cylinder head and on the glow pencils are cleaned particularly thoroughly.
- Apply a suitable sealant to the thread of the glow pencils.
- Tighten the glow pencils with the prescribed torque.

Bulletin